

Estill Middle School



1572BZ
PICT-518



1572CA
PICT-519



1572CB
PICT-520



1572CC
PICT-521



1572CD
PICT-522

1572CE
PICT-523



1572CF
PICT-524



1572CG
PICT-525





1572CH
PICT-526



1572CI
PICT-527



1572CJ
PICT-528



1572CK
PICT-530



1572CL
PICT-531




1572CM
PICT-532



1572CN
PICT-533

1572CO
PICT-534



A close-up photograph showing the intersection of a ceiling and a carpet. The ceiling is made of white acoustic tiles, and the carpet is dark brown. There is significant damage along the joint, with the carpet material peeling away from the ceiling, revealing a layer of drywall or plaster underneath. Several small, pinkish-purple circular marks are visible on the carpet near the damaged area. In the bottom left corner, a portion of a wooden chair is visible.

**1572CP
PICT-535**



1572CQ
PICT-536



1572CR
PICT-537



1572CS
PICT-538



1572CT
PICT-539



1572CU
PICT-540

1572CV
PICT-541





1572CW
PICT-542



1572CX
PICT-543



1572CY
PICT-544




1572CZ
PICT-545



1572DA
PICT-546



1572DB
PICT-547



1572DC
PICT-548



1572DD
PICT-549